

Fairlington Commons Council of Co-Owners

December 30, 2010

Introduction

The Fairlington Commons Council of Co-Owners must assess the long-term needs of the Commons and ensure that adequate funds to meet those needs are available. Those funds can come from two sources - current year assessments; i.e., the current operating budget, or from reserve funds, which is money held over from prior year assessments.

An inventory of items requiring capitol investment is essentially provided in the line items of the Fairlington Commons operating budget and includes:

Buildings

- Paint
- Fences
- Decks
- Gutters
- Roofs
- Plumbing
- Other Building Features

Grounds

- Turf
- Lighting
- Shrubbery & Trees
- Sidewalks
- Parking Lots
- Other Grounds Features--Retaining Walls

Recreation Facilities

- Swimming Pool
- Other Recreation Facilities

In general, this study will discuss all aspects of each item of the inventory and will:

1. Explain the nature of the items,
2. Assess the condition of the items and estimate their life expectancy,
3. Estimate the item's replacement costs,
4. Recommend, where applicable, methods for reducing repair cost or extending the item's life to help avoid premature replacements; and,
5. Plan for adjusting the operating budget and developing adequate reserves to meet needs over an extended period of time.

Fairlington Commons Council of Co-Owners Capital Replacement Study

A further goal of this study will be to meet the requirements of the Virginia Condominium Act with respect to reserves for capital components. That Act states:

§ 55-79.83:1. Reserves for capital components.

A. Except to the extent otherwise provided in the condominium instruments and unless the condominium instruments impose more stringent requirements, the executive organ shall:

- 1. Conduct at least once every five years a study to determine the necessity and amount of reserves required to repair, replace and restore the capital components;*
- 2. Review the results of that study at least annually to determine if reserves are sufficient; and*
- 3. Make any adjustments the executive organ deems necessary to maintain reserves, as appropriate.*

B. To the extent that the reserve study conducted in accordance with this section indicates a need to budget for reserves, the unit owners' association budget shall include, without limitations:

- 1. The current estimated replacement cost, estimated remaining life and estimated useful life of the capital components;*
- 2. As of the beginning of the fiscal year for which the budget is prepared, the current amount of accumulated cash reserves set aside, to repair, replace or restore the capital components and the amount of the expected contribution to the reserve fund for that fiscal year; and*
- 3. A general statement describing the procedures used for the estimation and accumulation of cash reserves pursuant to this section and the extent to which the unit owners' association is funding its reserve obligations consistent with the study currently in effect.*

Capital Investments in Buildings

Building Painting

A majority of the exterior surface area of our buildings is unpainted red brick, with the exception of the structure within the pool facility, which is constructed from unpainted white “split block” concrete block.

The Commons paints those exterior features that require painting, including porches, columns, doorframes and doors, windows frames and windows, concrete basement window wells, and window well grates. Duron Signature Lifetime Exterior 914 White has been used for a majority of the trim. A limited number of standard colors are used for doors – the basement window well grates are painted black.

The Commons is also responsible for a limited amount of interior painting, including the common areas of our Apartment-style buildings, the common areas associated with our Georgetown-style buildings, and pool facility rooms.

Fairlington Commons Council of Co-Owners Capital Replacement Study

Exterior painting is done on a three-year cycle, with 74 to 79 units painted each year. Interior painting is done less frequently and on an as-needed basis. Lampposts and grates are painted on an as-needed basis, and rear doors are painted on a six-year cycle. At the beginning of each year, one third of the Commons needs exterior painting, one third will need it in one year, and one third will need it in two years.

Fairlington Commons was originally painted with oil-based paint and the earliest layers contain lead paint. From 2007 through 2009 wood in the Commons was painted with Duron Signature Lifetime paint, a premium latex “self priming paint” recommended for wood that had been painted with oil based paint.

Preparation for painting is still accomplished by scraping and scuffing, although the Commons continues to monitor evolving paint removal technology in search of a more cost effective method. Hard sanding is not a viable option due to lead paint in the earliest layers. Co-Owners who replace windows are required to cap window frames with aluminum or vinyl to reduce long-term wood replacement and painting costs.

Annual costs for the three-year cycle from 2009 through 2011 will be approximately \$43,000 per year, with an approximate 10 percent variation due to the different numbers and styles of the units being painted each year. Painting is funded from annual revenue with no need to draw on reserve funds. No significant adjustments in annual revenues are required to sustain this work in the future.

Fences and Decks

The Commons is responsible for the repair and replacement of approximately 6000 linear feet of wood patio fence, 175 gates, and 36 decks serving 44 units. Most fences are associated with multiple units; some decks also serve more than one unit. There are about six co-owner installed decks that are not the responsibility of the Commons. Commons fences and decks have been left a natural color since the mid-1980s. Co-owners are permitted to use a clear sealant on fences and decks, but not paint or stain them.

Work on decks is of three types. First, minor repairs have been made on an as-needed basis. Second, the surfaces of the decks (and the railings) have been replaced. Third, entire decks, including the supporting posts and stringers, have been replaced. In general, the surfaces have about half the life expectancy of the entire deck. The life expectancy, however, has varied substantially based on exposure and upkeep by owners. Replacing the surface and railings costs roughly half the amount of replacing the entire deck, including posts and stringers. Some surfaces have lasted only a decade while others have lasted two decades. The decks, for the most part, have not needed to be replaced all at once. The most deck replacement in one year was four decks serving five units, with one or two decks serving one or two units per year being the norm. Decks rebuilt during the replacement cycle that is now being completed are heavier duty than the original decks

Fairlington Commons Council of Co-Owners Capital Replacement Study

and show every indication of lasting longer than the older decks. Two old decks need to be replaced by 2012 at a total cost of approximately \$10,000. The life expectancy of the remaining decks is to 2025 or beyond, with replacement of some surfaces beginning by 2015. Many decks do not cover the entire patio area, so the cost of deck replacement varies substantially with size of the deck.

Fences were replaced over the six-year period from 1984 to 1989. The fence replacement cycle commenced in 2009 and will continue for roughly a 10-year period. The estimated cost of all fencing and gates was estimated at \$200,000 at 2005 prices. Actual expenditures for fence replacement for three buildings in April of 2009 were 9% above the 2005 estimate for the same fences.

Fences and decks are repaired on an as-required basis to avoid the need for premature replacement. Repairs are funded from the annual operating budget. Use of synthetic deck surfaces with natural wood posts was evaluated in 2007 and found to be approximately 35 - 40% more expensive and thus not cost effective.

Fences and decks will continue to be replaced from annual revenue with no reserve funding required. \$28,500 was approved for fence and deck work in 2010, although substantially less work was done to offset the cost of storms. No significant adjustments in annual revenues are required to sustain this work in the future.

Gutters

Most gutters in the Commons are aluminum. Into the 1990s the Commons replaced wood gutters with redwood gutters that were custom-milled, but discontinued this practice because aluminum gutters required less maintenance. Some of the old Cyprus or Redwood gutters that were installed prior to conversion to condominiums in 1972-3 remain. There is no risk of mass gutter or downspout failure. Older gutters or those that have sustained ice damage are replaced as required.

For 2006-2009, over \$11,000 per year was spent on gutter repair and replacement and roughly this amount, adjusted for inflation, is appropriate for the foreseeable future. In 2010 the Commons spent over \$17,000 in gutter repair and maintenance, but a substantial portion of this was covered by insurance for storm damage.

Gutter repair and replacement is funded from annual revenues. There is no need to fund this work from reserve funds. No significant adjustments in the annual revenues are required to sustain this work.

Plumbing

Maintenance and replacement of water supply lines from Arlington County mains to the individual units, and those supply lines common to more than one individual unit, are the responsibility of the Commons. Maintenance and replacement of sewer lines (laterals)

Fairlington Commons Council of Co-Owners Capital Replacement Study

between Commons buildings and Arlington County sewer mains, and those lines common to more than one individual unit, are also the responsibility of the Commons.

The Commons has used the same plumber and backup plumber for approximately 20 years and five years, respectively. The primary plumber has camera equipment for diagnosing problems within sewer lines and uses this equipment frequently. While there is no evidence that the sewer lines are nearing total failure, they have aged to a point where some line repair or replacement is required each year. In general, the water supply system is in good condition.

The Commons has explored relining pipes as a preventative measure. Fairlington Glen, a neighboring condominium association, started to undertake relining, but found that the cost exceeded replacement when the cost of the prep work was added to the cost of relining. This information is consistent with the estimates and contingencies presented to the Commons by a contractor that specializes in relining.

The Commons spent an average of about \$18,000 per year from 2005 - 2008 on plumbing. In both 2009 and 2010 over \$30,000 was spent on plumbing in order to replace/reline five lateral sewer lines each year before they failed. The preventative replacement of lateral lines should be planned each year. All plumbing is funded from annual revenues and there is no foreseeable need to fund this work from reserve funds. No significant adjustments in the annual revenues are required to sustain this work.

Roofs

Preventative maintenance, repair, and replacement of roofs are potentially our largest long-term capital expense. Our 54 buildings house 229 units that, due to their architectural diversity, are covered by 68 slate roofs, 7 tile roofs, and 6 flat tar roofs.

Commons roofs vary substantially in life expectancy, from some that are essentially at the end of their life span, to original roofs that, assuming proper maintenance, have a half century of life remaining. Seven Vermont slate roofs covering 17 units were installed from about 2003 through 2007 and are expected to last a century.

In 2002 and 2005, our roofing contractor provided an estimate of the life expectancy of each tile and slate roof in the Commons. Basically, the roofs over 200 of our units will need to be replaced over the next 50 years, with a slightly higher pace anticipated during the next 10 to 15 years. In actuality, some neighboring Fairlington associations have been able to slow the pace of their roof replacements because the life expectancies provided by this same roofer were proving overly pessimistic.

In 2007 the Commons investigated the cost and practicality of using high quality synthetic slate instead of natural slate. The initial cost of replacement was substantially lower, with significantly reduced maintenance costs (e.g., no ridges to be sealed). Two buildings (9 units--two Edgewoods, two Georgetown, and a Fairlington) were re-roofed

Fairlington Commons Council of Co-Owners Capital Replacement Study

with synthetic slate in 2008 and three more buildings were re-roofed in 2009. .In 2010, five buildings of four types were re-roofed with synthetic slate. Approximate costs, including painting chimney caps and minor carpentry repairs, for different kinds of buildings are:

Unit Types	Year	Approximate Cost
Barcroft Lower (2) & Buckingham (2)	2010	\$15,000
Clarendon/Clarendon End	2010	17,000
Edgewood/Edgewood End	2010	17,000
Georgetown/Georgetown w Yard/Fairlington	2010	13,000
Bathhouse	2009	17,000

The synthetic slate has a diminishing coverage warranty over a 50 year period, with 90% of the coverage occurring in the first 15 years. Life expectancies generally exceed warranties, although we do not have estimates for how much beyond the warranty period, if any, synthetic slate roofs can be expected to last. Additional savings will be realized when synthetic slate is removed for future re-roofing.

The original tile is no longer manufactured for any of the tile roofs, which have a life expectancy of up to 40 years. They also will probably be replaced with a synthetic material.

Flat roofs have a nominal life expectancy of 15 years, but in practice the Commons has found they last much longer with periodic maintenance. One flat roof covering two units was replaced and all other flat roofs were resealed in 2008.

The Commons has established a roof maintenance program to extend the life of our roofs. *Ad hoc* repairs are made in response to immediate problems - damaged or missing slates, for example. Attention is paid to the condition of gaskets around vent stacks and to the flashing. For roofs with a life expectancy of 15 years or greater, the Commons conducts systematic maintenance that includes replacement of missing slates, ridge caulking, and flashing on a 12 to 15 year cycle.

The Commons increased the pace of roof replacement from three to five buildings in 2010. That pace will continue until about 2017, when all Bangor slate roofs will have been replaced. The roofs with Bangor slate are estimated to reach the end of their life expectancy by about 2020.. Roofing is funded from annual revenues and no use of reserve funds is foreseen.

Other Building Features – (Dormers, Brick Porches, Trim, Common Areas)

The carpet in the common areas (hallways, stairs and landings) of six apartment-style buildings is a Commons responsibility. All of it was replaced approximately 20 years ago. An inspection in 2009 showed that the carpet was generally holding up well, but it will probably have to be replaced within the next five years. As industrial grade carpet is

Fairlington Commons Council of Co-Owners Capital Replacement Study

used to meet the requirements of these high-traffic areas, replacement costs could approach \$20,000, to be funded from the annual operating budget.

Carpentry is performed on the exterior of all Commons buildings and in the common areas of our apartment style and Georgetown style buildings on an as-required basis. Masonry work is also performed on an as-required basis.

The dormers, brick porches, trim, and common areas of our buildings are in overall good condition with no major replacements anticipated in the foreseeable future. All dormers were replaced using redwood in the 1980's. Wood replacement is accomplished in conjunction with the painting cycle or on a case-by-case basis as required. Re-pointing of masonry (brick porches) is done as required. Several porches with underlying structural issues have already been replaced, and several will need to be replaced in the next five years at a cost of roughly \$7,500 each. The price varies with the number of steps.

Structural underpinning is an unforeseen, yet highly possible, variable. The Commons has underpinned buildings to restore structural integrity in the past and did so again in 2009.

Other building features are funded from annual revenue and no use of reserve funds in needed.

Capital Investments in Grounds

Turf

Fairlington Commons is responsible for maintenance of 22 acres of land, over half of which consists of lawns.

The Grounds are in good condition. Fertilizer, herbicides, and pesticides are applied within strict guidelines each year and reseeded is accomplished each fall to prevent the need for a capital investment in lawns. In some areas where tree shade makes it difficult to grow grass, other ground cover has been planted.

No major capital investments in the grounds are needed. Maintenance of grounds, as described above, is accomplished gradually over time with funds from current annual revenue.

Lighting and Fire Safety Equipment

There are 153 ornamental black post lamps located adjacent sidewalks throughout the Commons, controlled by 14 photoelectric sensors. As opposed to the larger, commercial style street lamps owned and maintained by Arlington County and Dominion Virginia

Fairlington Commons Council of Co-Owners Capital Replacement Study

Power, the Commons maintains the ornamental lamps, associated underground wiring, and the sensors that control them.

The ornamental black post lamps are in good condition. As a cost savings measure, the lamps have been equipped with low-wattage, long-life fluorescent bulbs. Periodic inspection, lamp and bulb replacement, repair of damaged lamps, and cleaning of the lenses is accomplished by a contractor retained by the Commons. Over time, 86 of the original lamps have been replaced, as have a number of the underground power lines. The remaining 67 original lights are in sound condition and do not show signs of requiring replacement in the near future or at the same time. The replacement cost of individual light fixtures was \$22 in 2010, exclusive of labor.

The Commons also maintains 43 lights and 18 smoke detectors in the general common areas within our six Apartment-style buildings. The same contractor who maintains our outdoor lighting provides this service. All lights and smoke detectors are in excellent condition as of December 2010. Each of the six buildings as well as the pool bathhouse is equipped with a fire extinguisher. These were replaced about 2003 and are in excellent condition. They are inspected and maintained annually by a qualified contractor.

Lighting and smoke detector maintenance and replacement is funded from annual revenue with no use of reserve funds.

Sidewalks

Sidewalk maintenance and replacement is the responsibility of the Commons, except for those sidewalks immediately parallel Arlington County public streets, which are the responsibility of the County.

Sidewalks in the Commons have varying life expectancies depending on when they were installed. New sidewalks are expected to last 50 years. Older walks will need replacement at varying times within the next 50 years, some within the next two years. For the last decade, an average of \$28,000 per year has been spent on sidewalk replacement, including the relatively expensive replacement of steps undertaken during this time period. \$25,000 - \$35,000 per year, with adjustment for inflation, is adequate funding for sidewalk replacement.

Sidewalk replacement is funded from annual revenue and no use of reserve funds is needed. Some walks should be replaced every year to avoid a backlog of deferred work.

Parking Lots

The 10 original parking lot surfaces lasted 25 years: from 1972 - 1973 until they were replaced in 1997 at a cost of \$101,000. The contractor who performed the replacement provided a conservative estimate for a surface life of 15 - 20 years, but with proper maintenance and care that life could extend beyond 20 years. The Commons believes

Fairlington Commons Council of Co-Owners Capital Replacement Study

that the new parking lot surfaces are in fact of higher quality than the originals and can match their 25-year life span.

Our parking lots are in good condition, and are of better quality than those originally installed in 1972 - 1973. In conjunction with the last resurfacing, improved drainage was installed in several lots, particularly the upper S. Utah Street Lot. A long-term problem with the lower S. Utah Street lot was corrected by excavation and installation of a gravel bed, providing a proper foundation for the asphalt.

Parking lot maintenance includes sealing the cracks on an as-needed basis and, less frequently, the application of asphalt rejuvenator. Based on this aggressive maintenance program, the Board views the anticipated lifespan of our parking lots at 25 years, with replacement in 2022. As all lots have the same life expectancy, they will all be repaved simultaneously to avoid additional overhead associated with spreading the work over a period of time.

In 2010 the same contractor who performed the work in 1997 and provided an estimate in 2004 estimated a new cost of \$160,000 to repave the lots. To derive a replacement cost for 2022, an annual inflation rate of 4.5% has been assumed. This is considerably higher than the 3.0% annual inflation rate experienced from 1990 to 1999 and the 2.9% rate experienced from 2000 to 2008. However, inflation for petroleum-based products has been higher than the overall rate of inflation in general, so adopting a higher rate for reserve planning purposes is prudent. The estimated replacement cost is approximately \$271,300 in 2022, requiring annual contributions of \$16,500. This level of contribution is included in the 2011 budget. It should be noted that if the useful life of the parking lots is shorter, the shortfall could be covered from the annual operating fund and/or the Unrestricted Reserve Fund. For example, using the same inflation and contribution rates, there would be less than a \$27,500 shortfall if the replacement were to occur after 20 years, in 2017. That amount could be easily covered by funding from the operating budget and the Unrestricted Reserve Fund. If a 3% rate of inflation is assumed, the paving reserve would have \$6,600 shortfall if paving were done in 2017 and a surplus in excess of \$44,000 if paving were done in 2022.

Parking lot maintenance is funded from annual revenues. Parking lot replacement will be funded from reserve funds.

Shrubbery and Tree Service

The large grounds maintenance contract does not include all work on shrubbery and trees. The cost of additional services to plant, prune, and remove shrubbery and trees in the general common areas and trees planted before conversion in the early 1970s is included in this part of the budget. \$12,000 was budgeted for shrubbery and tree work in 2010. Shrubbery and tree work, including replacements, is funded from annual revenues. A storm in 2010 caused extensive damage to our tree canopy, so costs for this line item are

Fairlington Commons Council of Co-Owners
Capital Replacement Study

expected to increase modestly. However, the additional work can be funded from annual revenues.

Other Grounds Features (Retaining Walls and Signs)

Retaining Walls

There are 22 masonry (stone) retaining walls and 29 timber retaining walls in the Commons.

The masonry retaining walls vary in condition and most date to the original construction in 1943 - 1944. Due to the amount of labor involved in repairing them, they represent a major potential capital expense. Four masonry walls, one of the largest and two of the smallest, have required rebuilding in 2001, 2007, 2008, and 2009. The costs were about \$20,000, \$5,000, \$5,000, \$6,000, respectively. In addition, extensive repairs were undertaken on a long stone retaining wall along a parking lot on Utah St. at a cost of \$4,500. Many of the smaller masonry retaining walls will require rebuilding or extensive repair within the next 10 to 15 years. Before the 2009 work was undertaken, competitive bids were solicited for nine retaining walls for future planning purposes.

Timber retaining walls have been replaced as needed. In 2007, the Commons Grounds Contractor did a survey of the timber retaining walls, categorizing them based on remaining life expectancy and providing a cost estimate for each wall:

Estimated Replacement Span	Number Of Timber Walls	Total Estimated Cost
2007-2011	8	\$12,250
2012-2016	10	\$15,800
2017-2021	11	\$23,775

There are additional retaining walls under and beside some decks that are usually replaced when the decks are replaced.

The rebuilding of retaining walls is funded from annual revenues. The budget for “Other Grounds Services” has been set at \$25,000 in order to meet this increased need. Some further minor adjustments will be needed from year to year. No use of reserve funds is needed.

Signs

The Commons has posted large, decorative redwood signs so that guests and safety vehicles can see the addresses of units in the adjacent court from the street. A separate

Fairlington Commons Council of Co-Owners Capital Replacement Study

redwood and metal sign immediately below advises that parking is reserved and towing enforced.

In addition to the redwood signs, there are a relatively small number of metal signs regarding dumping, trespassing, and identifying the Commons as private property.

The signs are in excellent condition. Some posts will need to be replaced in the next 20 years, but this can be done on an as-needed basis. A few of the metal signs are fading and may need to be replaced within the next 10 years on an as-needed basis.

All signs were originally purchased and installed with annual revenue. No need to use reserve funds for signs is foreseen.

Capital Investments in Recreation Facilities

Swimming Pool Facility

The Commons owns and operates a swimming facility for the use of our Co-Owners, residents, and their guests. The facility consists of a 100,000-gallon capacity 25-yard main pool, a 1,500-gallon capacity child's wading pool, a men's and women's bathhouse, lifeguard office, and a pump room. A 7-½ foot tall black-vinyl coated chain link fence surrounds the facility. It is approximately 421 feet in length with posts spaced at roughly 10-foot intervals. Within this area, the wading pool and adjacent deck is enclosed within a 3-foot tall black vinyl coated chain link fence approximately 114 feet in length. A concrete deck of 5,100 square feet starts at the pool entrance and runs in front of the bathhouse and office entrances and around both pools. The facility exterior is fully lighted. Within the enclosure there are six entryway lights, 10 pole lights with spherical globes, and three floodlights on the bathhouse capable of fully illuminating the entire enclosure. There are four 500-Watt lights located below the water in the main pool.

The facility was originally constructed in the early 1970s and has undergone several updates and renovations since, the most recent in 2002 when new main drains, returns, skimmers, tiles, and coping stones were installed, beam damage repaired, both pools white-coated, and concrete deck replaced around the deep and far ends of the main pool. To help prevent drowning or disembowelment accidents, dual drains were installed in the main pool; the wading pool drain does not connect directly to the pump. Covers were purchased and installed over both pools.

In addition to the 2002 renovation, extensive work was performed on the facility in 1998. Bathroom floors were removed and re-poured to correct drainage issues, and the toilet stalls, bench-seats, towel, and soap dispensers were replaced. The entire facility was rewired to correct serious safety issues with old, deteriorated wiring, and old lighting was renovated or replaced. Ground Fault Circuit Interrupter (GFCI) outlets were installed in

Fairlington Commons Council of Co-Owners Capital Replacement Study

all fixtures, and GFCI circuit breakers installed on circuits serving underwater or pump well devices. The facility complies with modern electrical code requirements.

The main and wading pools are in excellent condition. White coating is needed approximately every six to eight years. This was last performed in 2008. Although the estimated cost was \$17,700, due to extensive de-lamination of the previous layers of white coat, the actual cost was about \$21,500.

The concrete deck is also in excellent condition. Two sections were replaced in 2007; other sections have been replaced as needed over the years, most recently in conjunction with the 2002 renovation. The remaining sections of deck have an anticipated life expectancy of 10 to 30 years and will not need to be replaced all at one time. Based on 2007 prices, the replacement cost of the total deck would be approximately \$130,000 - \$135,000.

The extensive 1998 renovation of the structure that contains the bathhouse, lifeguard office, and pump room cost roughly \$42,000, but none of that work will have to be repeated in the foreseeable future. The roof of the bathhouse was replaced in 2009 with synthetic slate.

The fence surrounding the facility is scheduled for repair in 2011. The replacement cost was estimated at \$10,500 in 2010. When the fence is replaced, the side gate should be widened to permit the entry of emergency and construction vehicles. The fence surrounding the wading pool was replaced more recently and is in excellent condition. Two competitive bids obtained in the fall of 2010 placed the cost of this fence at approximately \$2,000. It should not require repair or replacement in the foreseeable future.

The pump system is aging, but is otherwise in good condition and is maintained annually. Barring an unforeseen catastrophic failure, the system should continue to perform well into the future.

The main and wading pools are covered from September through March when they are not in use. The cover was purchased in 2002. The estimated replacement cost is \$10,000.

Most prior renovations have been paid from annual revenues. All work planned from 2008 through 2010 was funded from annual revenues. The Board plans to fund the next white coating of the pool from Reserve Funds. Annual reserve fund contributions of \$4,700 are required and have been budgeted. Otherwise, maintenance of the facility will be funded from the Operating Budget.

Other Recreation Facilities

The Commons maintains a picnic table, a basketball court, a tennis court, and a tot lot located within the Wakefield Street Circle.

Fairlington Commons Council of Co-Owners Capital Replacement Study

Picnic Table - The picnic table is a galvanized steel frame anchored in concrete with wood benches and table surface, 11 ½ feet in length. The wood is showing signs of weathering and will need to be replaced within the next five years. The steel frame is sound and appears not to require maintenance or replacement in the foreseeable future. The cost of the picnic table, including steel frame, is estimated at under \$1,000.

Basketball Court - The basketball court consists of a 45 by 50 foot concrete slab with backboards and hoops. It is in excellent condition. In 1995, a new concrete slab was poured, posts reset, and backboards, hoops, and nets replaced at a cost of about \$13,500. This work also included resolution of a drainage issue that directly contributed to the early deterioration of the previous playing surface. The slab remains in very good condition and should have a lifespan of 50 years or more. Poles, hoops and nets are replaced as needed, which is infrequent.

Tennis Court - The Commons has one tennis court. It is built on an asphalt slab measuring 108 feet by 59 feet, enclosed within a 10 foot high black vinyl coated chain link fence with posts spaced at roughly 10 foot intervals. There is a 6-foot, concrete anchored metal frame bench with a wood seat and back just outside the enclosure.

The tennis court was resurfaced and the fence replaced (most of the original posts were reused) in the 1993 - 1994 timeframe at a cost of \$41,000.- Cracks in the court were sealed and the surface repainted in 1996 and 2005 for about \$3,000 and \$5,000, respectively. The wood on the bench was replaced in about 2002 and the frame shows no signs of needing maintenance or replacement.

In 2008, the court surface began to crack and in 2009, more cracks appeared. The Board had planned to seal and repaint the surface at a cost of approximately \$5,000 for 2011, but this would extend the life of the surface only about 5 years. A 2010 estimate for resurfacing the court is about \$30,000. This work is planned for 2013, but may need to be done sooner, and will be funded from a reserve account established for the 2011 budget. Inflation has not been factored in because of the low current rate of inflation and the short period of time until the work will be done.

The fence is in excellent condition and will not need to be repaired or replaced in the near future.

Tot Lot - The tot lot is a 24 by 24 foot area with a substrate of wooden chips. Within this area are a vinyl double slide, a sliding pole, and a “tower” with a wooden ramp to reach the top of the slides and sliding pole. A six-foot bench, identical to the one at the tennis court, is located immediately adjacent the Tot Lot and is in very good condition. (A third identical bench is located behind 4627 S. 34th Street overlooking the woods and will need to have the wood replaced within the next one or two years.)

Fairlington Commons Council of Co-Owners Capital Replacement Study

The current Tot Lot was installed in 2002 following demolition of the original and was re-located farther from the street as a safety measure. The total cost, including demolition and relocation, was roughly \$4,000. With periodic renewal of chips and care for the equipment, the tot lot should last beyond 2027. The cost of replacing the slide and tower, including installation and removal of the old equipment, was estimated at \$1,500 in 2008. Wood chips need to be added to the area every few years. The Commons follows the policy of using only chips that are designed for tot lots, which is an added expense. The cost of adding chips in the spring of 2008 was \$975.

Work on recreation facilities other than the pool has been funded from annual revenues and no funding from reserve funds has been needed. The Board will assess whether reserve funds will be needed for resurfacing the tennis court and replacing the concrete slab for the basketball court.

Fairlington Commons Council of Co-Owners Capital Replacement Study

Financial Requirements

Fairlington Commons adopted a policy of spreading out capital replacements, where practical, in the 1980's. The Commons is painting, replacing roofs, sidewalks, retaining walls, fences and decks, and other capital features every year with fairly little variation in budget from year to year. Other capital features are staggered. For example, the tennis court is not resurfaced the same year the swimming pool is white-coated. Some upward adjustment in the budget will be required to increase the pace of replacing retaining walls and sewer lateral lines.

Repaving parking lots is one of two capital expenses planned for funding from reserves. The other is white coating the pool. Reserve contributions of roughly \$16,500 and \$4,700 per year, respectively are required to fund these items. These amounts are in the budget. Additions to the unrestricted reserve fund are also needed for unexpected emergencies.