

**August 5 Storm Damage, Insured Items, Fairlington Commons 5345PE024092**

**Report of August 16, 2010 9:00AM.**

The area was struck by a sudden afternoon storm with gusts about 70 mph.

John D. Sinks, President 703-931-2660 [jsinks@comcast.net](mailto:jsinks@comcast.net)

Eric Pamer, Service Coordinator 703-933-3839 [CommonsService@hotmail.com](mailto:CommonsService@hotmail.com)

**34<sup>th</sup> St.**

4697 to Rt 395. At least two trees fell and took about 4 sections chain link fence. Closer to 4697 the top of the fence was damaged. The trees have been removed from the fence.

4697 Gutter from dormer down into stairwell on back of unit.

4515-21 Tree uprooted and took up about a dozen feet of sidewalk. No work has been done on these trees.

4515 Loose shutter 2 fl. front.  
Two bent sidewalk lights in back.

4439 Large tree behind unit lost some large branches onto the back of the roof. These have been removed (crane work). Roof damage must be assessed.

4427 Shutter down second floor front

4417 Sidewalk pole light bent.

**Wakefield St.**

3363A&B Fence hit by maple. Other than some gate damage on the B unit patio fence reported by owner, damage not assessed. Nothing done with tree.

3367 Pine tree topped and fell onto end of tennis court, damaging the fence, including the corner pole. Broken tree pulled off of fence.  
Three globes blown off pole lights at pool.

3341 A Shutter down 2<sup>nd</sup> floor left; chimney screen found.

3315 Shutter down left side first floor.  
Tree uprooted, tearing up back of patio fence and retaining wall timbers, and fell across the end of the fence knocking it down. This was originally reported just as a tree down, so nothing has been done to clear the tree as I did not know insured structures were damaged.

3310B Two loose shutters and one down shutter reported by owner.

3314B Two shutters down from second floor left.

3336B Tree damaged patio fence behind unit and has been removed. Slate damage from falling branches.

3338B Slate damage  
**Utah St.**

3220 or 22 Light fixture in open area to side and behind the unit damaged.

3222 Shutter down second floor left.

3222-26 Tree onto the back of the roof of building hanging over the front, with most on 3224. Broken part removed from roof. Some slate damage on the ridge visible from front. Owner reports deck damaged by falling limb.

3228. Owner reports damaged gate

3230 Shutter down

3232 Shutter down

3234 Shutter down second floor left.

3236 Shutter dangling second floor right.

3238 Sidewalk pole light fixture damaged (One report had this light located at 3336.)

3244 Tree fell on deck. Does not appear to be damage to deck. No work done by association on this tree, but I think the owners cut some branches in order to use deck.

3250 Slate damage. Wind sheared a bunch right off and pulled others loose.  
Sidewalk pole light near back of unit wiped out by tree falling.

3254 Tree falling in back broke the deck railing and went through the window. Branches moved off deck and roof. Owner reports that now that the trees are clear he can see two punctures in the back of his roof.

3284 Left front shutter down.

3292 Large branches came down on fence and shed (shed not Commons responsibility) and hanging precariously. (This has been removed.) Fence not yet inspected for damage.